

# CERTIFICATE OF COMPLIANCE

**Certificate Number** E481791  
**Report Reference** E481791-20210430  
**Issue Date** 2021-APRIL-30

**Issued to:** FELM srl  
Via MorandiInverunoITMIIT20001

**This certificate confirms that  
representative samples of**

Motors for Appliance Applications - Component  
See Addendum Page

Have been investigated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.

**Standard(s) for Safety:** UL 1004-1- Standards for Rotating Electrical Machines - General Requirements.  
CSA C22.2 No. 100-14- Standard for Motors and generators

**Additional Information:** See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Recognized Component Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.



Bruce Mahrenholz, Director North American Certification Program  
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE

Certificate Number E481791  
Report Reference E481791-20210430  
Issue Date 2021-APRIL-30

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

\*\*\*-80G-2,\*\*\*-80G-4,\*\*\*-80K-2,\*\*\*-90L-2,\*\*\*-90L-4,\*\*\*-90L-6,\*\*\*-90S-2,\*\*\*-90S-4,\*\*\*-90S-6,\*\*\*-100L-2,\*\*\*-100L-4,\*\*\*-100L-6,\*\*\*-100LX-4,\*\*\*-112M-2,\*\*\*-112M-4,\*\*\*-112M-6,\*\*\*-132M-4,\*\*\*-132M-6,\*\*\*-132MX-6,\*\*\*-132S-2,\*\*\*-132S-4,\*\*\*-132S-6,\*\*\*-132SX-2,\*\*\*-160L-2,\*\*\*-160L-4,\*\*\*-160L-6,\*\*\*-160LX-2,\*\*\*-160LX-4,\*\*\*-160LX-6,\*\*\*-160LY-2,\*\*\*-180L-4,\*\*\*-180L-6,\*\*\*-180M-2,\*\*\*-180M-4,\*\*\*-200L-2,\*\*\*-200L-4,\*\*\*-200L-6,\*\*\*-200LX-2,\*\*\*-200LX-6,\*\*\*-225M-2,\*\*\*-225M-4,\*\*\*-225M-6,\*\*\*-225S-4,\*\*\*-250M-2,\*\*\*-250M-4,\*\*\*-250M-6,\*\*\*-280M-2,\*\*\*-280M-4,\*\*\*-280M-6,\*\*\*-280S-2,\*\*\*-280S-4,\*\*\*-280S-6,\*\*\*-315L-2,\*\*\*-315L-4,\*\*\*-315L-6,\*\*\*-315LX-2,\*\*\*-315LX-4,\*\*\*-315LX-6,\*\*\*-315M-2,\*\*\*-315M-4,\*\*\*-315M-6,\*\*\*-315S-2,\*\*\*-315S-4,\*\*\*-315S-6,\*\*\*-355L-2,\*\*\*-355L-4,\*\*\*-355L-6,\*\*\*-355LX-2,\*\*\*-355LX-4,\*\*\*-355LX-6,\*\*\*-355LY-2,\*\*\*-355LY-4,\*\*\*-355LY-6,\*\*\*-355M-2,\*\*\*-355M-4,\*\*\*-355M-6,\*\*\*-355MX-6,\*\*\*-355MY-6,\*\*\*-400M-2,\*\*\*-400M-4,\*\*\*-400M-6.

\*\*\*\*143T-2,\*\*\*\*143T-4,\*\*\*\*145T-2,\*\*\*\*145T-4,\*\*\*\*145T-6,\*\*\*\*182T-2,\*\*\*\*182T-4,\*\*\*\*182T-6,\*\*\*\*184T-2,\*\*\*\*184T-4,\*\*\*\*184T-6,\*\*\*\*213T-2,\*\*\*\*213T-4,\*\*\*\*213T-6,\*\*\*\*215T-2,\*\*\*\*215T-4,\*\*\*\*215T-6,\*\*\*\*254T-2,\*\*\*\*254T-4,\*\*\*\*254T-6,\*\*\*\*256T-2,\*\*\*\*256T-4,\*\*\*\*256T-6,\*\*\*\*284T-4,\*\*\*\*284T-6,\*\*\*\*284TS-2,\*\*\*\*286T-4,\*\*\*\*286T-6,\*\*\*\*286TS-2,\*\*\*\*324T-4,\*\*\*\*324T-6,\*\*\*\*324TS-2,\*\*\*\*326T-4,\*\*\*\*326T-6,\*\*\*\*326TS-2,\*\*\*\*364T-4,\*\*\*\*364T-6,\*\*\*\*364TS-2,\*\*\*\*365T-4,\*\*\*\*365T-6,\*\*\*\*365TS-2,\*\*\*\*404T-6,\*\*\*\*405T-4,\*\*\*\*405T-6,\*\*\*\*405TS-2,\*\*\*\*444T-4,\*\*\*\*444T-6,\*\*\*\*444TS-2,\*\*\*\*445T-4,\*\*\*\*445T-6,\*\*\*\*445TS-2,\*\*\*\*447T-4,\*\*\*\*447T-6,\*\*\*\*447TS-2,\*\*\*\*449T-4,\*\*\*\*449T-6,\*\*\*\*449TS-2,\*\*\*\*504/5T-4,\*\*\*\*504/5T-6,\*\*\*\*586/7T-4,\*\*\*\*586/7T-6,FWMP 400LY-4.



Bruce Mahrenholz, Director North American Certification Program  
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

